

Inspection Summary

2013 Porsche Panamera GTS

Inspection Details

Inspection Company	DataScan	Inspector	20596
Inspection Date	28/01/2016	Drivable	Yes

Vehicle Details

Unique Code	
VIN	WP0AF2A72DL076558
Company	DataScan
Transmission	AUTOMATIC
Body Style	SEDAN
Fuel Type	GAS
Interior Colour	BLACK
Exterior Color	BLACK
Mileage	44540
Odometer Condition	GOOD
Engine Displacement	4.8L

Inspection Images



Inspection Summary

Was Vehicle Test Driven?	No
Frame Damage?	No
Air Bag Light On?	No
Check Engine Light On?	No
Comments	

Parts Inspected

PARKING ASSIST REAR	PARKING ASSIST FRONT
HEATED MIRROR	CARGO COVER
MULTIFUNC. WHEEL	FRONT HEAT
CLIMATE CONTROL	Air Conditioning
# AIR BAGS : 10	TILT
REAR DEFROSTER	POWER WINDOWS
POWER TILT WHEEL	POWER STEERING
POWER SEATS	POWER MIRROR
POWER LOCKS	POWER BRAKES
MEMORY SEATS	HEATED SEATS
HEADLIGHT WASHER	CRUISE
ABS	USB Port
SATELLITE RADIO BUTTON	NAVIGATION DISC
GPS	CD
AUXILIARY	AM/FM
POWER SUNROOF	UPHOLSTERY TYPE : LEATHER
REAR SEAT STYLE : INDIVIDUAL	FRONT SEAT STYLE : INDIVIDUAL

Tyres

Description	Depth	Make	DOT	NSpec	Size
FRONT LEFT TIRE	5	PIRELLI	xt1hk4892115	N-0	20
FRONT RIGHT TIRE	8	PIRELLI	xt1hk4892115	N-0	20
REAR LEFT TIRE	6	PIRELLI	xt6fk4881014	N-0	20
REAR RIGHT TIRE	6	PIRELLI	xt6fk4880914	N-0	20
SPARE TIRE	0				0

Damage Details

Area	Region	Type	Total Estimate	Description	Estimated General Hrs	Estimated Metal Hrs	Estimated Paint Hrs	Estimated Parts Amount
FRONT BUMPER	EXTERNAL DAMAGES	1X18.0" CRACKED	3428.24	FRONT BUMPER	3.60	0.00	3.00	2636.24
FRONT LEFT TIRE	TIRE DAMAGES	SNOW TIRE	300.00	FRONT LEFT TIRE	0.00	0.00	0.00	300.00
FRONT RIGHT TIRE	TIRE DAMAGES	SNOW TIRE	300.00	FRONT RIGHT TIRE	0.00	0.00	0.00	300.00
REAR LEFT TIRE	TIRE DAMAGES	MISMATCHED - SIZE, SNOW TIRE	300.00	REAR LEFT TIRE	0.00	0.00	0.00	300.00
REAR RIGHT TIRE	TIRE DAMAGES	MISMATCHED - SIZE, SNOW TIRE	300.00	REAR RIGHT TIRE	0.00	0.00	0.00	300.00
KEYS	EQUIPMENT	NOT OPERATIONAL	200.00	KEYS	0.00	0.00	0.00	200.00
20K MILES	MECHANICAL DAMAGES	NO	0	20K MILES	0.00	0.00	0.00	0
40K MILES	MECHANICAL DAMAGES	NO	0	40K MILES	0.00	0.00	0.00	0
MAINT. MANUAL AVAILABLE	MECHANICAL DAMAGES	NO	0	MAINT. MANUAL AVAILABLE	0.00	0.00	0.00	0